

CLASSIFICATION

25X1A

REF ID: A65130

--	--	--	--	--	--	--	--	--	--

COUNTRY: Germany

DATE DISTR.: 1 June 1953

SUBJECT: Rolling Mill Production of Nonferrous Metals for

NO. OF PAGES: 1

First half of 1953 (Medium Plate)

25X1A

NO. OF ENCLS.: 1

CLASS
REQUIRED:SUPPLEMENT TO
REPORT NO.DATE OF
INFO:

THIS IS UNVERIFIED INFORMATION

25X1X

SOURCE:

1. For the first quarter of 1953, production in the rolling of nonferrous medium plate was as follows (all weights are in metric tons):
 - a. Sufficient orders have been placed at Walzwerk Hettstedt and it is expected that the quota assigned for the first quarter will be fulfilled.
 - b. Orders have been placed at the Halbzeugwerke Auerhainer amounting to 500 tons in excess of the assigned production quota. Auerhainer will probably experience difficulty in fulfilling even its production quota because of the poor delivery of plate bar. At present it will be impossible to roll 1,000 mm. sheet at Auerhainer because of a break in the roller chassis.
 - c. Orders have been placed at the Elektrwalzwerke Olbernhau amounting to about 50 tons in excess of the assigned production quota. Olbernhau is expected to fulfill these excess orders.
2. For the second quarter of 1953, plans for the production of medium plate of nonferrous metals are as follows:
 - a. Walzwerk Hettstedt has a rolling quota of 2,750 tons. An effort will be made to roll 3,000 tons.
 - b. Insufficient orders amounting to 750 tons were placed at the Halbzeugwerke Auerhainer by the former quota bearer Ministry for Machine Construction. Excess orders not filled during the first quarter will be carried over to the second quarter.
 - c. To date, orders amounting to only 2,800 tons have been placed at the Elektrwalzwerke Olbernhau. However, too many orders for 3 mm. plate have been placed.

CLASSIFICATION

SECRET

25X1

STATE	NAVY	NSPS	DISTRIBUTION						
			ORR	EV					
ARMY	AIR	FBI		X					

dgt

- 2 -

3. The Lettstedt, Olbernhau, and Auerhammer mills would experience no difficulty in rolling plate of 3 mm. thickness and over. Previous insufficient rolling of plate in this thickness was caused in each case by the sporadic and insufficient deliveries of plate bar from the Maxhütte Unterwölzenborn.